											2022 SH	OPP As of Octo	ober 2024 Close	e-Out								
<u>Dist</u>	County	Route	Post Miles	Location/Description	<u>EA</u>	<u>PPNO</u>	<u>Project ID</u>	Prog Code	<u>FY</u>	RW	Con	Vote	Vote Date	Fund Type	PA&ED	PS&E	RW Sup	Con Sup	Total Cap &	<u>Performance</u> Value	<u>Performance Measure</u>	Approved Baseline
10	Alpine	4	R0.000/31.700	Near Bear Valley, from Calaveras County line to Route 89; also on Route 89 at 0.9 mile north of Route 4 (PM 10.84). Rehabilitate pavement, replace guardrail and signs, place Rock Slope Protection (RSP), rehabilitate drainage systems, and enhance highway worker safety.  (G13 Contingency)	0Ј720	1044	1018000271	201.121	23-24	\$575	\$37,000	\$0	1/0/00	NH	\$2,213	\$2,196	\$1,076	\$4,887	\$up \$47,947		Lane mile(s)	Agreement
10	Alpine	4		In Alpine County, on Routes 4, 88, and 89 at various locations. Environmental mitigation for drainage rehabilitation project EA 0S680.	0\$681	3142A	1020000166	201.151	22-23	\$0	\$200	\$200	8/18/22	RMRA	\$0	\$229	\$0	\$400	\$829	0.00	Culvert(s) (ea)	
10	Alpine	88	1.900	Near Kirkwood, at the Caples Lake Maintenance Station. Reconstruct a dormitory and sand shed structures, and rehabilitate a generator building.	1H560	3433	1017000184	201.352	23-24	\$26	\$24,948	\$0	1/0/00	ST-CASH	\$853	\$2,526	\$50	\$4,148	\$32,551	1.00	Location(s)	
10	Alpine	89	14.900/R17.300	Near Markleeville, from Webster Street to Turtle Rock Park Road. Repair storm damaged washouts, ditches, and pavement, construct concrete apron and Rock Slope Protection (RSP), and remove debris.	1Q490	3562	1023000022	201.130	22-23	\$500	\$3,500	\$3,500	9/9/22	NH	\$200	\$0	\$100	\$400	\$4,700	1.00	Location(s)	
10	Alpine	207	0.300	Near Bear Valley, at 0.3 mile north of Route 4; also at 0.38 mile north of Route 4 (PM 0.38); also in Amador county near Plymouth on Route 16, 0.1 mile west of Route 124 (PM 8.97). Environmental mitigation for drainage rehabilitation project EA 0S750.	0\$751	3138A	1020000159	201.151	22-23	\$ \$0	\$170	\$325	8/17/23	RMRA	\$0	\$204	\$0	\$136	\$510	0.00	Culvert(s) (ea)	
10	Alpine	Var		In Alpine County, at various locations. Environmental mitigation for EA 0X750.	0X753	3134A	1021000016	201.112	22-23	\$1,653	\$0	\$0	1/0/00	RMRA	\$325	\$205	\$361	\$0	\$2,544	0.00	Linear feet rail	
10	Amador	88	5.500/14.300	Near Martell, from Route 124 to Route 49. Rehabilitate pavement, modify traffic signals, upgrade guardrail, and rehabilitate drainage systems. This project will extend the pavement service life and improve ride quality.	0Q210	0167	1017000171	201.121	23-24	\$126	\$11,516	\$11,921	8/16/24	NH	\$980	\$1,708	\$104	\$1,674	\$16,108	19.70	Lane mile(s)	
10	Amador	88	32.500/70.000	Near Kirkwood, from 0.3 mile east of Wagon Wheel Drive to 0.7 mile west of Kirkwood Lake Road; also in Alpine County, on Route 88, 4, and 89 at various locations; also in Calaveras County, on Route 4 at various locations. Replace guard railing and snow gates, and install traffic delineation and erosion control.	1R890	3606	1023000244	201.130	23-24	\$ \$0	\$1,285	\$1,285	9/28/23	NH	\$30	\$0	\$0	\$225	\$1,540	52.00	Location(s)	
10	Amador	88	R54.700/R60.800	Near Kirkwood, from west of Foster Meadow Road to 1.1 miles east of Shot Rock Vista Point. Rehabilitate drainage systems and pave driveways.	0K130	2680	1012000002	201.151	23-24	\$100	\$3,811	\$2,910	8/16/24	RMRA	\$1,653	\$2,035	\$390	\$1,850	\$9,839	13.00	Culvert(s) (ea)	
10	Amador	88	68.000/R69.000	Near Kirkwood, from 2.1 miles west to 3.1 miles west of Kit Carson Road; also in Alpine County, near Sorensens, from 0.2 mile east to 1.2 miles east of Kit Carson Campground Road (PM 15.0/16.0). Repair storm damaged roadway, repair drainage ditches, debris removal, and install erosion control.	1R910	3605	1023000246	201.130	23-24	\$ \$0	\$800	\$800	8/15/23	NH	\$20	\$0	\$0	\$150	\$970	2.00	Location(s)	
10	Amador	88		In Amador, Calaveras, and San Joaquin Counties, on Routes 26, 49, and 88 at various locations. Remove debris, stabilize slopes, place rock slope protection, repair drainage systems, and install permanent erosion control.	1R380	3583	1023000138	201.130	22-23	\$ \$0	\$1,500	\$1,500	3/1/23	NH	\$50	\$0	\$50	\$200	\$1,800	11.00	Location(s)	

											2022 SH	OPP As of Octo		-Out								
<u>Dist</u>	County	Route	Post Miles	<u>Location/Description</u>	<u>EA</u>	PPNO	<u>Project ID</u>	Prog Code	<u>FY</u>	RW	Con	Vote	Vote Date	Fund Type	PA&ED	PS&E	RW Sup	Con Sup	Total Cap &	<u>Performance</u>	Performance Measure	Approved Baseline
10	Calaveras	4	32.400/37.400	Near Forest Meadows, from 1.4 miles east of Forest Meadows Drive to Moran Road; also on Route 49 in Calaveras County (PM 5.78/16.98) and Tuolumne County (PM 12.64/17.17) at various locations. Rehabilitate drainage systems.	1G620	3409	1017000181	201.151	23-24	\$236	\$4,297	\$0	1/0/00	RMRA	\$1,248	\$987	\$225	\$1,134	\$up \$8,127	<b>Value</b> 22.00	Culvert(s) (ea)	Agreement
10	Calaveras	12	9.900/10.300	Near Valley Springs, from Route 26 to west of Lime Creek Road (west). Intersection safety improvements.	1J820	3476	1019000055	201.010	23-24	\$1,764	\$3,852	\$0	1/0/00	STP	\$1,098	\$1,374	\$221	\$1,216	\$9,525	18.00	Collision(s) reduced	
10	Calaveras	12	17.100/17.600	Near San Andreas, from 0.2 mile west to 0.3 mile east of North Fork Calaveras Creek Bridge No. 30-0007. Replace bridge and realign roadway.	0X740	3288	1013000008	201.110	23-24	\$688	\$16,631	\$0	1/0/00	RMRA	\$1,072	\$2,093	\$90	\$2,500	\$23,074	1.00	Bridge(s)	
10	Calaveras	26	4.900/9.600	Near Valley Springs, from 0.1 mile west of Olive Orchard Road to 0.3 mile west of Hogan Dam Road. Repair embankment slopes, drainage systems, and pavement.	1R290	3578	1023000126	201.130	22-23	\$0	\$450	\$450	2/1/23	NH	\$70	\$0	\$0	\$70	\$590	4.00	Location(s)	
10	Calaveras	26	18.100	Near Mokelumne Hill, at the intersection with Route 49. Intersection improvements.	1K820	3494	1019000164	201.010	23-24	\$6,258	\$7,055	\$0	1/0/00	STP	\$1,610	\$1,759	\$668	\$1,602	\$18,952	22.00	Collision(s) reduced	
10	Calaveras	26	21.800/30.300	Near Mokelumne Hill and West Point, at various locations from 3.6 miles east of Route 49 to 0.9 mile south of Woodhouse Mine Road. Stabilize failing and eroded slopes.	0V480	3132	1013000264	201.407	23-24	\$1,355	\$7,743	\$7,742	3/22/24	NH	\$1,323	\$1,000	\$718	\$3,442	\$15,581	3.00	Location(s)	
10	Calaveras	49	7.400/9.500	In and near Angels Camp, on Main Street from Pine Street to Brunner Hill Road. Upgrade facilities to Americans with Disabilities Act (ADA) standards, construct new sidewalk and class 2 bike lanes as complete streets elements.	1H700	3429	1018000277	201.361	23-24	\$471	\$5,204	\$7,959	10/18/24	NH	\$1,417	\$1,508	\$2,571	\$1,120	\$12,291	26.00	Curb ramp(s)	
10	Calaveras	49	18.700/20.200	Near San Andreas, from south of Toyanza Street to north of Pool Station Road. Upgrade facilities to Americans with Disabilities Act (ADA) standards and construct complete streets improvements.	1G270	3435	1018000013	201.361	23-24	\$884	\$9,200	\$0	1/0/00	NH	\$1,922	\$2,126	\$1,235	\$1,998	\$17,365	49.00	Curb ramp(s)	
10	Mariposa	49	32.600	Near Bagby, at 3.1 mile north of Bear Valley Road; also on Route 140 near Briceburg, from 1.6 to 0.6 mile south of Bull Creek Road (PM 32.5/33.5); also in Tuolumne County, near Moccasin, from 0.6 to 0.3 mile south of Jackass Gulch Bridge (PM 2.4/2.7). Remove loose material from slopes, repair cable netting system, repair damaged pavement, and place erosion control.	1R640	3588	1023000186	201.130	22-23	\$0	\$1,500	\$1,500	4/27/23	NH	\$20	\$10	\$0	\$250	\$1,780	3.00	Location(s)	
10	Mariposa	140	28.330	Near Midpines, at Bear Creek Br. No. 40-0003. Repair bridge and embankment scour.	1R760	3595	1023000220	201.130	22-23	\$0	\$500	\$500	5/16/23	NH	\$20	\$0	\$0	\$75	\$595	1.00	Location(s)	
10	Mariposa	140	35.000	Near Briceburg, at 0.9 mile east of Briceburg Road. Remove debris, stabilize slope, replace pavement, and place permanent erosion control.	1R250	3577	1023000122	201.130	22-23	\$0	\$700	\$700	1/31/23	NH	\$20	\$10	\$0	\$100	\$830	1.00	Location(s)	
10	Merced	5		In Merced County, on Routes 5, 59, and 152 at various locations. Repair damaged pavement and replace striping.	1R400	3586	1023000140	201.130	22-23	\$0	\$6,997	\$6,997	4/3/23	NH	\$100	\$0	\$0	\$900	\$7,997	232.00	Location(s)	
10	Merced	33	R0.600/1.500	In and near Dos Palos, from Stearman Street to 0.1 mile north of Santos Street; also in Gustine on Route 140 from 0.1 mile east of Jensen Road to 2nd Street (PM 4.8/6.2). Upgrade facilities to Americans with Disabilities Act (ADA) standards and install flashing beacon.	1G250	3441	1018000276	201.361	22-23	\$310	\$5,170	\$5,114	8/17/23	NH	\$1,134	\$1,594	\$200	\$1,330	\$9,738	67.00	Curb ramp(s)	

											2022 SH	OPP As of Octol		-Out								
<u>Dist</u>	County	<u>Route</u>	Post Miles	<u>Location/Description</u>	<u>EA</u>	PPNO	<u>Project ID</u>	Prog Code	<u>FY</u>	RW	<u>Con</u>	(\$1,000 <u>Vote</u>	<del></del>	Fund Type	PA&ED	PS&E	RW Sup	Con Sup	Total Cap &	<u>Performance</u>	Performance Measure	Approved Baseline
10	Merced	59	R0.000/12.100	Near Merced, from Route 152 to Reilly Road. Rehabilitate pavement, upgrade guardrail and lighting, replace sign panels, construct rumble strips, rehabilitate drainage, replace one bridge, and rehabilitate two bridge decks. (G13 Contingency)	0V690	3439	1018000284	201.121	23-24	\$908	\$20,020	\$0	1/0/00	NH	\$1,415	\$1,962	\$610	\$2,639	\$27,554	<b>Value</b> 24.00	Lane mile(s)	Agreement
10	Merced	59	13.600	Near the city of Merced, at the intersection with Gerald Avenue. Intersection improvements.	1K620	3466	1019000059	201.010	23-24	\$1,343	\$4,565	\$0	1/0/00	STP	\$1,036	\$1,588	\$495	\$1,113	\$10,140	22.00	Collision(s) reduced	
10	Merced	99	0.400/R12.700	In and near the city of Merced, from north of the Madera County line to south of East Childs Avenue. Construct median barrier.	1L310	3510	1020000183	201.010	22-23	\$23	\$13,399	\$7,675	3/24/23	STP	\$894	\$1,384	\$51	\$1,856	\$17,607	124.00	Collision(s) reduced	
10	Merced	99	21.600/23.500	In Atwater, at East Atwater Overhead No. 36-0126L/R; also at West Atwater Overhead No. 39-128L/R. Apply polyester concrete overlay to bridge decks. (Bridge Deck Preservation)	1N780	3534	1022000026	201.119	22-23	\$5	\$3,471	\$2,876	3/23/23	RMRA	\$100	\$350	\$5	\$600	\$4,531	4.00	Bridge(s)	
10	Merced	99	24.500/28.200	Near Atwater, from 0.5 mile south of Westside Boulevard to 0.8 mile south of Hammatt Avenue. Upgrade guardrail to current standards. This project will reduce the number and severity of collisions.	07610	3442	1013000245	201.015	22-23	\$20	\$3,224	\$3,155	1/26/23	STP	\$677	\$1,374	\$20	\$783	\$6,098	5.00	Collision(s) reduced	
10	Merced	99	R29.800/R30.200	In Livingston, from 0.6 mile south to 0.2 mile south of Winton Parkway. Repair damaged embankment, stabilize multiple utilities, and install erosion control.	15010	3627	1024000010	201.130	23-24	\$0	\$800	\$800	8/21/23	NH	\$20	\$0	\$40	\$130	\$990	1.00	Location(s)	
10	Merced	140	43.500/43.900	Near Planada, from west of Plainsburg Road to Sutter Street. Intersection improvements.	1M170	3506	1020000188	201.010	23-24	\$2,760	\$4,520	\$0	1/0/00	STP	\$1,090	\$1,530	\$410	\$1,450	\$11,760	17.00	Collision(s) reduced	
10	Merced	152	R10.100/13.848	Near Los Banos, from 0.8 mile west Basalt Road to Route 5. Construct cable median barrier to improve safety. This project will reduce the number and severity of collisions.	1L630	3505	1020000085	201.010	23-24	\$110	\$6,407	\$5,000	8/18/23	STP	\$1,010	\$1,070	\$138	\$1,130	\$9,865	58.00	Collision(s) reduced	
10	Merced	152		In Merced County, on Routes 152, 140, and 59 at various locations. Seismic retrofit and bridge rail upgrade of seven bridges, apply polyester concrete overlay on Bridge No. 39-0034L/R and architectural treatment on Bridge No. 39-0009L/R.	0G830	3122	1012000316	201.113	22-23	\$1,700	\$13,500	\$13,661	3/23/23	HBRR-S	\$982	\$3,000	\$400	\$3,000	\$22,582	7.00	Bridge(s)	
10	Merced	165	11.700	In Merced County, on Routes 165, 5, 33, and 140 at various locations; also in Stanislaus County on Route 5 at Route 140 Juncion (PM 0.0). Widen shoulders to accommodate truck turning movements, rehabilitate pavement and drainage system, install Transportation Management System (TMS) elements, and replace signs.		3447	1017000177	201.310	23-24	\$683	\$5,100	\$0	1/0/00	NH	\$840	\$920	\$290	\$950	\$8,783	144.60	Daily vehicle hour(s) of delay (DVHD)	
10	Merced	165	32.900	Near Hilmar, at the intersection with Geer Avenue. Signalize intersection. This project will improve safety and reduce the number and severity of collisions.	1L870	3498	1020000086	201.010	23-24	\$1,512	\$2,655	\$2,849	9/18/24	STP	\$1,800	\$1,910	\$790	\$1,249	\$9,916	9.00	Collision(s) reduced	
10	San Joaquin	4	0.010	Near Discovery Bay, at Old River Bridge No. 29-0045; also on Route 12, in the community of Terminous at Little Potato Slough Bridge No. 29-0101 (PM R4.44). Repair vandalized maritime navigational facilities including submarine cables and beacon.	1R990	3623	1024000006	201.130	23-24	\$0	\$975	\$975	8/29/23	NH	\$50	\$0	\$0	\$200	\$1,225	2.00	Location(s)	

											2022 SH	OPP As of Octo (\$1,00)		-Out								
<u>Dist</u>	County	<u>Route</u>	Post Miles	Location/Description	<u>EA</u>	PPNO	<u>Project ID</u>	Prog Code	<u>FY</u>	RW	Con	Vote Vote	Vote Date	Fund Type	PA&ED	PS&E	RW Sup	Con Sup	Total Cap &	<u>Performance</u>	Performance Measure	Approved Baseline
10	San Joaquin	4	0.100	Near Discovery Bay, at Old River Bridge No. 29-0045. Install walers, place polyester concrete overlay, paint steel bridge, and remove abandoned garage.	1H360	3276	1017000185	201.119	23-24	\$495	\$7,801	\$5,802	8/16/24	RMRA	\$1,591	\$1,321	\$0	\$2,480	\$up \$13,688	Value	Bridge(s)	Agreement
10	San Joaquin	4	14.150	In Stockton, at San Joaquin River Bridge No. 29-0050. Repair fire damaged bridge and replace rock slope protection.	1R880	3600	1023000243	201.130	23-24	\$0	\$990	\$990	8/2/23	NH	\$50	\$0	\$0	\$200	\$1,240	1.00	Location(s)	
10	San Joaquin	4	R16.000/R19.400	In Stockton, from Route 5 to Route 99. Install ramp meters, traffic monitoring systems, Closed Circuit Television (CCTV), and synchronize intersection signals with ramp metering.	1F180	3274	1016000077	201.315	22-23	\$604	\$39,097	\$27,698	5/18/23	NH	\$2,177	\$6,057	\$695	\$9,438	\$58,068	14.00	Field element(s)	Aug-2020 / SHOPP-P-2021-01B
10	San Joaquin	4	R16.200	In Stockton, at Mormon Slough Bridge No. 29. 0237L. Apply polyester concrete overlay to bridge deck. (Bridge Deck Preservation)	- 1N760	3531	1022000024	201.119	22-23	\$0	\$1,970	\$1,298	5/18/23	RMRA	\$40	\$150	\$0	\$261	\$2,421	1.00	Bridge(s)	
10	San Joaquin	4	19.500/38.100	Near Stockton, from Route 99 to Stanislaus County line (PM 38.059); also in Stanislaus County line (PM 38.059); also in Stanislaus County from San Joaquin County line to 0.5 mile east of Dunton Road (PM 0.0/7.2). Rehabilitate pavement, upgrade guardrail, construct rumble strips, upgrade facilities to Americans with Disabilities Act (ADA) standards, rehabilitate drainage systems, install Transportation Management System (TMS) elements, and upgrade bridge railing.  (G13 Contingency)	1C050	3277	1017000178	201.121	23-24	\$379	\$36,437	\$0	1/0/00	NH	\$2,660	\$2,701	\$657	\$5,250	\$48,084	50.80	Lane mile(s)	
10	San Joaquin	4	20.500/20.900	Near Stockton, from 0.1 mile east of Del Rey Court to 0.2 mile east of South Walker Lane. Construct a channelized left-turn lane by widening the highway. This project will improve safety and reduce the number and severity of collisions.	1L280	3492	1020000103	201.010	23-24	\$261	\$2,429	\$2,570	9/26/24	STP	\$847	\$1,305	\$431	\$820	\$6,093	18.00	Collision(s) reduced	
10	San Joaquin	4	36.700	Near Farmington, at 0.3 mile west of Waverly Road. Repair embankment, drainage systems, and guardrail.	1R200	3573	1023000112	201.130	22-23	\$0	\$500	\$500	1/18/23	NH	\$20	\$0	\$0	\$75	\$595	1.00	Location(s)	
10	San Joaquin	4		In Stockton, on Routes 4 and 99 at various locations. Repair failed slopes, shoulders, dikes, pavement, and drainage systems.	1R170	3574	1023000109	201.130	22-23	\$0	\$900	\$900	1/18/23	NH	\$20	\$0	\$0	\$75	\$995	1.00	Location(s)	
10	San Joaquin	5	0.600	Near Lathrop, at the southbound Route 5 to westbound Route 580 Separation Bridge No. 29-0242L. Apply polyester concrete overlay to bridge deck, replace joint seals, repair unsound concrete and conform pavement at approach and departure slabs. (Bridge Deck Preservation)	1N770	3533	1022000025	201.119	22-23	\$0	\$1,300	\$1,369	5/18/23	RMRA	\$120	\$180	\$0	\$290	\$1,890	1.00	Bridge(s)	
10	San Joaquin	5	26.500/26.900	In Stockton, at Stockton Channel Viaduct No. 29-0176R/L. Repair spalled pavement on bridge decks and approach slabs.	1R360	3580	1023000135	201.130	22-23	\$0	\$3,500	\$3,500	3/1/23	NH	\$20	\$50	\$0	\$500	\$4,070	2.00	Location(s)	
10	San Joaquin	5	32.500/49.819	In and near Stockton, from Hammer Lane to the Sacramento County line (PM 49.819). Rehabilitate roadway, upgrade lighting, guardrail and bridge railing, install Transportation Management System (TMS) elements, replace signs, rehabilitate drainage systems, enhance highway worker safety, and upgrade facilities to Americans with Disabilities Act (ADA) standards. This project will improve safety and ride quality.	1E300	3427	1018000273	201.120	22-23	\$69	\$98,116	\$106,733	8/17/23	NH	\$2,108	\$4,153	\$162	\$10,953	\$115,561	83.40	Lane mile(s)	Jun-2022 / SHOPP-P-2122-07B

											2022 SH	OPP As of Octo		-Out								
<u>Dist</u>	County	<u>Route</u>	Post Miles	Location/Description	<u>EA</u>	PPNO	<u>Project ID</u>	Prog Code	<u>FY</u>	RW	Con	Vote Vote	Vote Date	Fund Type	PA&ED	PS&E	RW Sup	Con Sup	Total Cap &	<u>Performance</u> Value	Performance Measure	Approved Baseline
10	San Joaquin	5		In San Joaquin County, on Routes 5, 4, 12, 26, 33, 88, 99, 120, and 205 at various locations. Upgrade Transportation Management System (TMS) elements, including vehicle detection systems, road weather information systems, and closed circuit TV cameras.	1F960	3422	1018000007	201.315	23-24	\$25	\$9,090	\$7,960	8/16/24	RMRA	\$962	\$1,436	\$158	\$1,559	\$up \$13,230	40.00	Field element(s)	Agreement
10	San Joaquin	5		In San Joaquin County, on Routes 5 and 99 at various locations. Repair damaged pavement and replace striping.	1R410	3585	1023000141	201.130	22-23	\$0	\$2,547	\$2,547	5/21/23	NH	\$50	\$0	\$0	\$400	\$2,997	36.00	Location(s)	
10	San Joaquin	88	5.100/16.400	Near Lockeford, east of Comstock Road to east of Disch Road. Rehabilitate pavement, upgrade facilities to Americans with Disabilities Act (ADA) standards, reconstruct rumble strips, lengthen merge lanes, replace signs, upgrade Transportation Management System (TMS) elements, construct Class 2 and 3 bike lanes and sidewalks as complete streets elements.  (G13 Contingency)	1M590	7546	1021000012	201.121	23-24	\$4,265	\$27,333	\$0	1/0/00	NH	\$2,168	\$2,267	\$800	\$3,977	\$40,810	22.60	Lane mile(s)	
10	San Joaquin	99	0.000/7.000	In and near Manteca, Ripon and Salida, from south of Hammett Road to north of Yosemite Avenue at various locations. Pave areas behind the gore, construct Maintenance Vehicle Pullouts (MVPs), and slope pave beneath abutments to reduce maintenance needs and enhance highway worker safety.	1H530	3298	1017000204	201.235	22-23	\$55	\$2,289	\$2,722	12/8/22	NH	\$444	\$826	\$10	\$715	\$4,339	13.00	Location(s)	
10	San Joaquin	99	28.200/31.700	In and near Lodi, from south of Harney Lane to north of Turner Road. Pave areas behind the gore, install fence, place vegetation control barriers, slope pave beneath abutments, and construct Maintenance Vehicle Pullouts (MVPs) to reduce maintenance and enhance highway worker safety.	1H510	3407	1017000203	201.235	22-23	\$45	\$5,506	\$2,044	6/29/23	NH	\$758	\$822	\$11	\$1,085	\$8,227	17.00	Location(s)	
10	San Joaquin	99	28.700/31.700	In and near Lodi, from north of Harney Lane to north of Turner Road. Rehabilitate landscaping and irrigation system.	1H650	3428	1018000282	201.210	22-23	\$0	\$3,424	\$3,843	6/29/23	NH	\$442	\$815	\$12	\$1,085	\$5,778	14.00	Acre(s)	
10	San Joaquin	120	R1.200/T6.600	In and near Manteca, from 0.7 mile east of Route 5 to Route 99. Construct median barrier.	1L260	3509	1020000084	201.010	23-24	\$28	\$3,311	\$3,076	11/7/23	STP	\$881	\$1,613	\$101	\$1,011	\$6,945	0.23	Annual fatal and serious injury collision(s)	
10	San Joaquin	120	R2.300	In Manteca, at McKinley Avenue Undercrossing No. 29-0273R. Repair void in bridge approach slab.	1R650	3589	1023000187	201.130	22-23	\$0	\$500	\$500	4/18/23	NH	\$20	\$0	\$0	\$75	\$595	1.00	Location(s)	
10	San Joaquin	120	R3.320	Near Manteca, at Airport Way Overcrossing No. 29-0274 (PM R3.32); also in Stanislaus County, near Turlock and Ceres, on Route 99 at Keyes Road Overhead No. 38-0156Y (PM R7.81) and Hatch Road Overcrossing No. 38-0081Y (PM R13.28). Repair sinkhole, damaged pavement, gutters, eroded embankments, and collapsed guardrail.	1\$110	3634	1024000026	201.130	23-24	\$0	\$722	\$722	6/28/24	NH	\$20	\$0	\$0	\$110	\$852	3.00	Location(s)	
10	San Joaquin	120	11.600	Near Manteca, at French Camp Road. Construct signalized intersection.	1K460	3477	1019000084	201.010	23-24	\$700	\$7,699	\$0	1/0/00	STP	\$1,660	\$1,598	\$591	\$1,819	\$14,067	25.00	Collision(s) reduced	
10	San Joaquin	205	L0.000/R13.200	In and near Tracy, from Alameda County line to Route 5. Construct concrete anchor blocks for transition railing connects at structure approaches, upgrade guardrail, end treatments, and crash cushions to current standards to reduce the number and severity of collisions.	1C380	3474	1018000272	201.015	22-23	\$42	\$5,011	\$5,262	5/18/23	STP	\$794	\$1,348	\$19	\$868	\$8,082	7.00	Collision(s) reduced	

											2022 SH	OPP As of Octo (\$1,000		-Out								
<u>Dist</u>	County	<u>Route</u>	Post Miles	<u>Location/Description</u>	<u>EA</u>	PPNO	<u>Project ID</u>	Prog Code	<u>FY</u>	RW	Con	Vote Vote	Vote Date	Fund Type	PA&ED	PS&E	RW Sup	Con Sup	Total Cap &	<u>Performance</u>	Performance Measure	Approved Baseline
10	San Joaquin	580	11.500	Near Tracy, at West Valpico Overhead No. 29-0083R (PM 11.5) and East Midway Overhead No. 29-0082R (PM 12.7); also on Route 5 at Anderson Street Undercrossing No. 29-0229 (PM 25.6). Repair spalled pavement on bridge decks and approach slabs.	1R390	3582	1023000139	201.130	22-23	\$0	\$500	\$500	2/8/23	NH	\$20	\$20	\$0	\$75	\$up \$615	<b>Value</b> 3.00	Location(s)	Agreement
10	Stanislaus	5	10.300/25.500	Near Patterson, from Fink Road Undercrossing No. 38-0114L to Khaksa Road Undercrossing No. 38-0127L/R at various locations. Rehabilitate bridge decks with concrete overlay, replace joint seals and approach slabs, and rehabilitate columns.	1H280	3420	1017000190	201.110	22-23	\$22	\$9,814	\$9,774	8/17/23	RMRA	\$894	\$1,947	\$15	\$1,919	\$14,611	20.00	Bridge(s)	
10	Stanislaus	5	27.000/27.400	Near Westley, at the Westley Safety Roadside Rest Area (SRRA). Replace SRRA buildings, add walkways, site facilities, new fire access, and construct a California Highway Patrol (CHP) field office and maintenance crew room.	1C270	3144	1014000097	201.250	22-23	\$17	\$17,166	\$19,381	8/17/23	NH	\$0	\$529	\$15	\$3,750	\$21,477	2.00	Location(s)	
10	Stanislaus	5		In Stanislaus and San Joaquin Counties, on Routes 5, 120, and 580 at various locations. Remove debris, stabilize slopes, place rock slope protection, repair drainage systems and pavement, and install permanent erosion control.	1R350	3581	1023000134	201.130	22-23	\$0	\$1,500	\$1,500	2/16/23	NH	\$20	\$20	\$0	\$225	\$1,765	4.00	Location(s)	
10	Stanislaus	5		In Stanislaus County, on Routes 5 and 33 at various locations. Repair damaged pavement and replace striping.	1R420	3584	1023000142	201.130	22-23	\$0	\$3,093	\$3,093	4/20/23	NH	\$50	\$0	\$0	\$450	\$3,593	67.00	Location(s)	
10	Stanislaus	99	R1.500/R16.000	In and near Turlock, Ceres, and Modesto, from Route 165 to K Street. Clean and repair drainage systems, stabilize embankments, and place erosion control.	1R770	3594	1023000221	201.130	22-23	\$0	\$400	\$400	4/20/23	NH	\$20	\$0	\$0	\$60	\$480	4.00	Location(s)	
10	Stanislaus	99	R4.500/R23.300	In Stanislaus and San Joaquin Counties, on various routes at various locations. Install Transportation Management System (TMS) elements, and enhance highway worker safety.	1F970	3443	1018000283	201.315	23-24	\$607	\$8,935	\$11,451	10/18/24	RMRA	\$1,100	\$1,420	\$250	\$2,000	\$14,312	69.00	Field element(s)	
10	Stanislaus	99	R11.000/R11.500	In Ceres, from 0.9 mile south to 0.4 mile south of East Whitmore Avenue. Repair sinkhole including replacing culvert, repair pavement and replace traffic striping.	1R930	3619	1023000253	201.130	23-24	\$0	\$700	\$700	8/3/23	NH	\$20	\$0	\$0	\$125	\$845	1.00	Location(s)	
10	Stanislaus	99	R14.900	In Modesto, near Zeff Road Undercrossing. Construct stormwater Best Management Practices (BMPs) and a trash full capture device. This project will maximize pollution source control and prohibit trash from being discharged into the Tuolumne River.		3475	1017000187	201.335	22-23	\$0	\$1,061	\$695	6/29/23	NH	\$416	\$938	\$38	\$691	\$3,144	19.00	Acre(s) treated/pollutant	
10	Stanislaus	108	33.400	In Riverbank, at Claus Road intersection. Intersection improvements.	1K840	3490	1019000165	201.010	23-24	\$801	\$2,965	\$0	1/0/00	STP	\$1,501	\$1,611	\$314	\$1,407	\$8,599	11.00	Collision(s) reduced	
10	Tuolumne	120	R1.000	Near Oakdale, 0.3 mile west of Tulloch Road Remove debris, install drainage system, and repair embankment slope and shoulder.	1R180	3575	1023000110	201.130	22-23	\$0	\$1,000	\$1,000	1/18/23	NH	\$20	\$0	\$0	\$150	\$1,170	1.00	Location(s)	
10	Tuolumne	120	R3.400/R39.800	Near Groveland, from 4.7 miles west of La Grange Road to west of Ferretti Road; also ir Calaveras County, on Routes 12 and 26 and in Tuolumne County, on Route 108 at various locations. Rehabilitate drainage systems.	1F250	3411	1017000179	201.151	23-24	\$420	\$3,100	\$0	1/0/00	RMRA	\$1,182	\$1,181	\$251	\$1,307	\$7,441	39.00	Culvert(s) (ea)	
10	Tuolumne	120	7.300	Near Keystone, at Green Springs Road. Repair culvert and repair eroded slope.	1R370	3592	1023000137	201.130	22-23	\$0	\$600	\$600	4/11/23	NH	\$20	\$0	\$0	\$90	\$710	1.00	Location(s)	

											2022 SH	OPP As of Octo		-Out								
<u>Dist</u>	County	<u>Route</u>	Post Miles	Location/Description	<u>EA</u>	PPNO	<u>Project ID</u>	Prog Code	<u>FY</u>	RW	Con	(\$1,00 <u>Vote</u>	- /	Fund Type	PA&ED	PS&E	RW Sup	Con Sup	Total Cap & Sup	Performance Value	Performance Measure	Approved Baseline Agreement
10	Tuolumne	120	29.000/R54.000	Near Buck Meadows, from 1.2 miles west of Big Oak Road to 0.2 mile west of Golden Arrow Road. Repair storm damage, including debris removal, culvert replacement, roadway reconstruction, and slope stabilization.	1R680	3590	1023000205	201.130	22-23	\$0	\$1,000	\$1,000	4/20/23	NH	\$20	\$0	\$0	\$150	\$1,170		Location(s)	
10	Tuolumne	120	48.350	Near Buck Meadows, at 1.0 mile east of Sweetwater Road. Stabilize and repair failed embankment and place slope drainage systems.	1T090	3649	1024000174	201.130	23-24	\$0	\$1,274	\$1,274	4/3/24	NH	\$45	\$0	\$0	\$150	\$1,469	1.00	Location(s)	
10	Tuolumne	120	48.700/49.500	Near Groveland, from 1.4 miles east to 2.2 miles east of Cherry Lake Road. Remove debris, repair embankment slopes, pavement and drainage systems.	1R240	3576	1023000121	201.130	22-23	\$0	\$600	\$600	2/7/23	NH	\$20	\$0	\$0	\$80	\$700	1.00	Location(s)	
10	VAR			In Amador and Alpine Counties, on Route 26 and Route 89 at various locations. Remove debris, repair slope, replace drainage systems, and repair roadway.	1R730	3591	1023000212	201.130	22-23	\$0	\$800	\$800	5/15/23	NH	\$20	\$0	\$0	\$125	\$945	2.00	Location(s)	
10	VAR	Var		In Mariposa, Calaveras and Amador Counties at the Merced, Los Banos, Modesto, and Stockton Maintenance Stations. Repair and replace fencing, gates and gate controls. This project will utilize the Emergency Limited Bid contract method.	15490	3659	1024000087	201.352	23-24	\$0	\$1,999	\$1,999	6/28/24	ST-CASH	\$0	\$0	\$0	\$100	\$2,099	4.00	Location(s)	
10	VAR	Var		In Mariposa, Calaveras and Amador Counties at the Altaville, Midpines, Ione and Pine Grove Maintenance Stations. Repair and replace fencing, gates and gate controls. This project will utilize the Emergency Limited Bid contract method.	1\$520	3658	1024000090	201.352	23-24	\$0	\$2,001	\$2,001	6/28/24	ST-CASH	\$0	\$0	\$0	\$100	\$2,101	4.00	Location(s)	